AMZS d.o.o.
Cenitve in ostali pregledi vozil
Dunajska 128a
1000 Ljubljana

NLB Lease&Go d.o.o.
Flajšmanova ulica 3
1000 Ljubljana

CENILNO POROČILO

OSEBNI AVTOMOBIL (M1)

BMW IX XDRIVE AUT

VIN: **WBY11CF080CJ50722**

Ljubljana, 18.09.2026

IZJAVA CENILCA

Po svojem najboljšem poznavanju in prepričanju izjavljam, da:

- so v cenilnem poročilu uporabljeni podatki in informacije preverjeni v skladu z možnostmi ter uporabljeni v dobri veri, pri čemer verjamem in zaupam v njihovo točnost
- so prikazane analize, mnenja in sklepi omejeni samo s predpostavkami in omejevalnimi okoliščinami ter predstavljajo moje osebne , nepristranske in strokovne analize, mnenja in sklepe
- nimam sedanjih ali prihodnjih interesov v zadevi, ki je predmet tega cenilnega poročila, ter nimam osebnih interesov in nisem pristranski glede oseb, katerih se cenilno poročilo tiče
- je cenitev vozila opravljena na osnovi pregleda vozila in s tem poročilom ne prevzemam odgovornosti za prikrite napake na vozilu, ki jih v sklopu takšnega pregleda ni možno ugotoviti,
- cenilno poročilo odraža stanje vozila v trenutku pregleda, zato ne prevzemam odgovornosti za kasnejše poškodbe ali nastale nepravilnosti na vozilu, ki bi nastale po pregledu,
- plačilo za mojo storitev v zvezi z cenilnim poročilom ni vezano na vnaprej določen izid zadeve, ki bi bil ugoden za stranke v sporu ali doseganje dogovorjenega rezultata cenilnega poročila ali pojava kakršnega koli dogodka, povezanega s tako obliko dogovora
- mi ni nihče nudil pomembne strokovne pomoči oziroma, da so osebe, ki so mi podajale kakršnekoli informacije in podatke, navedene v poglavju Viri informacij

Blaž Boštjančič
Cenilec avtomobilske stroke



1. NAMEN IZDELAVE CENILNEGA POROČILA

Na podlagi naročila smo si ogledali: OSEBNI AVTOMOBIL (M1) znamke: BMW IX s številko šasije: WBY11CF080CJ50722 z namenom:

- da določimo trenutno stanje vozila (iztrošenost, ohranjenost, okvare)
- da določimo in ovrednotimo poškodbe ter nastalo škodo na vozilu
- kalkulacija naj bo narejena po tehnologiji proizvajalca in pravil stroke
- da določimo njegovo tržno vrednost, upoštevajoč starost vozila, prevožene kilometre, poškodbe na vozilu, tržni položaj ter splošno ohranjenost vozila

Pregled je opravil Blaž Boštjančič dne 15.09.2026 v podjetju , MAKŠE.

2. PREDMETNO VOZILO (TEHNIČNI PODATKI)

2.1. TEHNIČNI PODATKI

VRSTA VOZILA	OSEBNI AVTOMOBIL (M1)
ZNAMKA	BMW
KOMERCIALNA OZNAKA VOZILA	IX XDRIVE AUT
REG. ŠT.	/
ŠTEVILKA ŠASIJE	WBY11CF080CJ50722
PROSTORNINA MOTORJA	/
MOČ MOTORJA	/
VRSTA GORIVA	elektrika
DATUM PRVE REGISTRACIJE	01.12.2021
BARVA VOZILA	E0M (kovinski - BELA - SREDNJA)
ŠTEVILO SEDEŽEV	5
MASA VOZILA	2440 kg
NAJVEČJA TEHNIČNO DOVOLJENA MASA VOZILA	3010 kg
OBLIKA KAROSERIJE	AC KARAVAN

2.2. POMEMBNI PODATKI:

STAROST VOZILA OB PREGLEDU	4 leta in 9 mesecev
ŠT. PREVOŽENIH KM OB OGLEDU	126908 km

Slika 1: prednja leva diagonala vozila (S01)



Slika 2: zadnja desna diagonala vozila (S02)



Slika 3: VIN številka: WBY11CF080CJ50722



Slika 4: število kilometrov: 126908 km



3. UGOTOVITVE OB PREGLEDU

3.1. **ZUNANJOST:**

Na vozilu je vidnih nekaj odrgnin in poškodb pločevine in odbijačev.
Te poškodbe znižujejo tržno vrednost tega rabljenega vozila.
Opažene poškodbe:

Slika R01: Držalo pokrova motorja
Slika R02: Pokrov motorja
Slika R03: Sprednji odbijač
Slika R04: Vetrobransko steklo
Slika R05: Al platišče
Slika R06: Blatnik levi
Slika R07: Vzvratno ogledalo levo
Slika R08: Blatnik levi
Slika R09: Sprednja vrata leva
Slika R10: Zadnja vrata leva
Slika R11: Al platišče
Slika R12: Stranica leva
Slika R13: Pokrov prtljažnika
Slika R14: Zadnji odbijač
Slika R15: Al platišče
Slika R16: Zadnja vrata desna
Slika R17: Vzvratno ogledalo desno
Slika R18: Blatnik desni
Slika R19: Al platišče
Slika R20: Maska

Slika R01-1: Manjka
Slika R02-1: Vdolbina in poškodba laka
Slika R03-1: Poškodba laka
Slika R04-1: Poškodba
Slika R05-1: Popraskano
Slika R06-1: Poškodba laka
Slika R07-1: Poškodba
Slika R08-1: Poškodba laka
Slika R09-1: Poškodba
Slika R10-1: Poškodba laka
Slika R11-1: Popraskano
Slika R12-1: Poškodba laka
Slika R13-1: Poškodba laka
Slika R14-1: Poškodba laka
Slika R15-1: Popraskano
Slika R16-1: Poškodba
Slika R17-1: Poškodba
Slika R18-1: Poškodba
Slika R19-1: Popraskano
Slika R20-1: Poškodba


Slika R01: Držalo pokrova motorja



Slika R01-1: Manjka



Slika R02: Pokrov motorja



Slika R02-1: Vdolbina in poškodba laka



Slika R03: Sprednji odbijač



Slika R03-1: Poškodba laka



Slika R04: Vetrobransko steklo



Slika R04-1: Poškodba



Slika R05: Al platišče



Slika R05-1: Popraskano



Slika R06: Blatnik levi



Slika R06-1: Poškodba laka



Slika R07: Vzvratno ogledalo levo



Slika R07-1: Poškodba



Slika R08: Blatnik levi



Slika R08-1: Poškodba laka



Slika R09: Sprednja vrata leva



Slika R09-1: Poškodba



Slika R10: Zadnja vrata leva



Slika R10-1: Poškodba laka



Slika R11: Al platišče



Slika R11-1: Popraskano



Slika R12: Stranica leva



Slika R12-1: Poškodba laka



Slika R13: Pokrov prtljažnika



Slika R13-1: Poškodba laka



Slika R14: Zadnji odbijač



Slika R14-1: Poškodba laka



Slika R15: Al platišče



Slika R15-1: Popraskano



Slika R16: Zadnja vrata desna



Slika R16-1: Poškodba



Slika R17: Vzvratno ogledalo desno



Slika R17-1: Poškodba



Slika R18: Blatnik desni



Slika R18-1: Poškodba



Slika R19: Al platišče




Slika R19-1: Popraskano



Slika R20: Maska



Slika R20-1: Poškodba



Vetrobransko steklo lažje poškodovano. Ostala stekla in stekla vzvratnih ogledal niso poškodovana.
Brisalci so ustrezni.

Pnevmatike na vozilu:

Lega	Znamka in tip	Vrsta	Dimenzija	Starost	Globina profila
1. os	CONTINENTAL WINTER CONTACT	zimske	275/40/22	DOT 32/24	7
2. os	CONTINENTAL WINTER CONTACT	zimske	275/40/22	DOT 32/24	7

Pnevmatike so dimenzijsko ustrezne, starostno primerne in z dovolj profila.

Slika G01: 1. os dimenzija



Slika G02: 1. os starost



Slika G03: 2. os dimenzija



Slika G04: 2. os starost



Pri pregledu debeline laka sem ugotovil, da vozilo **ni** bilo reparaturno lakirano.

3.2. **NOTRANJOST:**

Notranjost vozila je v solidnem stanju.
Ugotovljene pomanjkljivosti:

- Polica prtljažnika - manjka

Slika N01: spredaj levo



Slika N02: volan z opremo



Slika N03: zadaj levo



Slika N04: prtljažnik



Slika N05: Polica prtljažnika



Slika N05-1: Manjka



3.3. **MOTORNI PROSTOR**

Zadnji servis opravljen 03.10.2024 pri 88592 km, glede na servisni interval ni potrebno opraviti servisa.


<u>Kmalu je potrebno opraviti servisni pregled.</u>

Ob priklopu na diagnostično orodje so bile ugotovljene napake.

Slika M01: motorni prostor



Slika M02: motor




Slika M04: servisna knjižica




Slika M05:




Slika M06:



Slika M07:



Slika M08:



Slika M09:



3.4. **DOKUMENTACIJA**

V vozilu je:

- Prometno dovoljenje
- Ključ, rezervni ključ
- Navodila za uporabnika
- Homologacija

Slika D01: navodila za uporabo



Slika D02: ključi



3.5. **OPREMA**

V vozilu se nahaja naslednja oprema:

- Obvezna oprema
- Set za popravilo pnevmatike

- Navigacija
- GSM inštalacija
- Vlečna kljuka

Slika O01: obvezna oprema



Slika O04: kit za popravilo pnevmatike




Slika O05: gasilnik



Slika O06: vlečna kljuka



Slika O07: navigacija



Slika O08:



Slika O09:



Slika O10:



Slika O11:



Slika O12:



Slika O13:



Slika O14:



Slika O15:



Slika O16:



Slika O17:



Slika O18:



Slika O19:



Slika O20:



Slika O21:



Slika O22:



Slika O23:




Slika O24:



Slika O25:



Slika O26:



3.6. **PREIZKUŠNJA VOZILA**

Motor: Vžge in deluje.

Klima: Deluje. Gretje sedežev deluje.

Svetlobna telesa: Delujejo.

Diagnostika: Opravljena - zaznane napake. (PRILOGA 3)

Testna vožnja: Neopravljena.

Podvozje: Podvozja v danih razmerah ni bilo mogoče pregledati.

V vozilu sta dva polnilna kabla.

Morebitne nepravilnosti na vozilu, ki bi se pokazale z daljšo vožnjo ni bilo možno ugotoviti in tudi niso upoštevane pri vrednotenju vozila.

Vehicle Diagnostic Report

The Report is created by SmartSafe

Repair Shop

Shop Name: Cenitve-AMZS

Address: Dunajska cesta 128a Ljubljana Slovenija

Zip Code: 1000

Telephone:

Email: cenitve@amzs.si

SN: 988150001890

Test Time: 2026-09-15 01:53:40

Technician Name:

Customer Name:

Vehicle Information

Year: 2021.11

Make: BMW

Model: iX xDrive40

VIN: WBY11CF080CJ50722

Odometer: 126909 km

Vehicle Software Version: V51.70

Diagnostic Application Version: V1.01.025

Diagnostic path: Automatically Search

System fault code(Pre-Repair)

UCAP (Ultrasonic Camera Automated Parking) 2 problems exist ⊙ADAS		
1.8031CA	Ultrasonic Sensors, Front: Extraneous Noise	Intermittent
2.8031CB	Ultrasonic Sensors, Rear: Extraneous Noise	Intermittent
HRSNR (Rear Radar Sensor Near Range Right) 1 problem exist ⊙ADAS		
1.7E0183	HRSNR: Lack Of Visibility	Intermittent
HKFM (Tailgate Function Module) 2 problems exist		

1.80170E	Restricted Availability Of HKL Function	Intermittent
2.80177C	HKFM, Automatic Operation Of Tailgate: Locking Detected	Intermittent
BCP21 (Basic Central Platform) 10 problems exist		
1.03034D	Steering Column Switch Cluster (SZL): Communication Fault	Intermittent
2.030E43	Power Management, Battery Condition Recognition: Standby Current Violation	Intermittent
3.8040C3	KL30F: Request Deactivation Due To Standby Current Violation	Intermittent
4.8040C6	KL30F: Request Reset Due To Standby Current Violation	Intermittent
5.8040D2	PRD Status: Activation Of Parking Status, Vehicle Electrical System Not OK	Intermittent
6.804262	Exterior Mirror Flaps (LIN): Repeat Lock Active	Intermittent
7.80448A	Rain-Light-Solar-Condensation Sensor (LIN): Excess Temperature	Intermittent
8.804924	Windscreen Wipe Function Available To A Limited Extent	Intermittent
9.80492D	Electric Folding-In Function Not Available	Intermittent
10.CD0600	BCP: Ethernet: Communication Fault (Loss Of Signal)	Permanent
EME (Electrical-Machine Electronics) 3 problems exist		
1.CE14B0	No Message (Speed, Vehicle, 0x1A1), Receiver EME, Transmitter DSC	Intermittent
2.CE1898	Message (- 0x12B80110) Missing, Receiver EME, Transmitter BDC-ZGM / BCP	Permanent
3.CE189C	Message (- 0x12B80310) Missing, Receiver EME, Transmitter BDC-ZGM / BCP	Permanent
FRSF (Long-Distance Range Front Radar Sensor) 6 problems exist ⊙ADAS		
1.0586B2	Front-Collision Warning With Brake Intervention Function Restricted Availability	Intermittent
2.0586B4	Front-Collision Warning With Brake Intervention Function Restricted Availability	Intermittent
3.0586B6	Front-Collision Warning With Brake Intervention Function Restricted Availability	Intermittent
4.0586B8	Front-Collision Warning With Brake Intervention Function Restricted Availability	Intermittent
5.D15513	Invalid Signal (Driver Assistance, Monitoring Head Movement Camera), Transmitter ADCAMM	Intermittent
6.D155F4	Signal (Sensor System Objects, Detection Of Front Radar Object List) Invalid, Transmitter ADCAMM	Intermittent
MPAD (Medium Platform Automatic Driving) 15 problems exist		
1.482E8E	Wrong-Way Warning Function Not Available	Intermittent

2.482E8F	Front-Collision Warning With Brake Intervention (Crossroads Warning) Function Not Available	Intermittent
3.D1940C	Message (Chassis, Load Cell End Of Line Provision) Missing, Receiver MPAD, Transmitter BCP	Intermittent
4.D19418	Message (Chassis, Target Value Of Braking Torque Provision) Missing, Receiver MPAD, Transmitter BCP	Intermittent
5.D19421	Message (Chassis, Status Of Brake Control System Function Provision) Missing, Receiver MPAD, Transmitter BCP	Intermittent
6.D19445	No Message (Running Gear, Provision Of Intrinsic Motion Signal), Receiver MPAD, Transmitter VIP	Intermittent
7.D19468	Invalid Signal (Sensors Detection, Detection Of Side Radar Sensor Object List), Transmitter RSNECU	Intermittent
8.D194B7	Message (Driver Assistance, Brake Warning Light Coordination) Missing, Receiver MPAD, Transmitter BCP	Intermittent
9.D194C9	No Message (Running Gear, Self-Movement, Odometry), Receiver MPAD, Transmitter VIP	Intermittent
10.D194CB	Signal (Running Gear, Self-Movement, Odometry) Invalid, Transmitter VIP	Permanent
11.D194D8	Invalid Signal (Driver Assistance, Evasion Assistant), Transmitter FRSF	Intermittent
12.D194DB	Message (Drivetrain, Accelerator Pedal Angle) Missing, Receiver MPAD, Transmitter BCP	Intermittent
13.D1950A	Signal (Navigation Disclosure Driver Assistance Prediction, Navigation System Information) Invalid, Transmitter HU	Permanent
14.D19522	Invalid Signal (Sensors Landmarks, Detection Of Front Camera Landmarks), Transmitter ADCAMM	Intermittent
15.D195A0	Signal (Body, Windscreen Wiper) Invalid, Transmitter BCP	Intermittent
MPAD2 (Medium Platform Automatic Driving 2) 2 problems exist		
1.D1E713	Message Checksum Incorrect (Drive, Drivetrain Data), Receiver MPAD2, Transmitter CCU / DME/DDE	Intermittent
2.D1E712	Signal Invalid (Drive, Drivetrain Data), Transmitter CCU / DME/DDE	Permanent
HRSNL (Rear Radar Sensor Near Range Left) 1 problem exist ⊙ADAS		
1.7E0182	HRSNL: Lack Of Visibility	Intermittent
VIP (Virtual Integration System) 12 problems exist		
1.030848	Restricted Availability Of Distance Control (ACC With Stop&Go) Function	Intermittent
2.030846	Restricted Availability Of Cruise Control With Brake Function	Intermittent
3.03084F	Speed Limit Info Function Not Available	Intermittent
4.030849	Traffic Light Detection Function Not Available	Intermittent

5.D76822	No Message (Body, 0x41F), Receiver VIP, Transmitter BCP / MPAD2	Intermittent
6.D76472	No Message (Ride Height Of Vehicle 2, 35.0.4), Receiver VIP, Transmitter VDP / BCP	Intermittent
7.D764EC	Signal (Driver Assistance, 0xFA) Invalid, Transmitter ADCAML / BCP / HPAD / MPAD	Intermittent
8.D764F0	Signal (Driver Assistance, 0xFC) Invalid, Transmitter ADCAML / BCP / HPAD / MPAD	Intermittent
9.D765F3	Signal (Driver Assistance, 0x1B1) Invalid, Transmitter ADCAML / BCP / HPAD / MPAD	Intermittent
10.D76677	Signal (Driver Assistance, 0x236) Invalid, Transmitter ADCAML / ADCAMM	Intermittent
11.D765F7	Signal (Driver Assistance, 0x1B8) Invalid, Transmitter ADCAML / ADCAMM / BCP	Intermittent
12.D7654A	No Message (Driver Assistance, 0xFB), Receiver VIP, Transmitter BCP / MPAD2	Intermittent
CCU (Combined Charging Unit) 3 problems exist		
1.224F81	AC Charging: Function Not Available	Intermittent
2.031B92	AC Charging, Charging Function: Charging Fault Detected By Charge Management	Intermittent
3.03194B	Charging, Power Line Communication: Connection Failure, Charging Station	Intermittent
SAMV (Front Smartphone Tray Module) 1 problem exist		
1.8056C5	SAMV: Temporary Functional Limitation: Foreign Body Detected	Intermittent
FZD (Roof Function Centre) 3 problems exist		
1.801A4A	Anti-Theft Alarm System: Tilt Sensor And Interior Movement Detector Deactivated	Intermittent
2.DE8C10	Panoramic Glass Sunroof Control Electronics: LIN Component Does Not Respond	Intermittent
3.801A10	Sky Lounge Function Not Available	Intermittent
ADCAMM (Mid Autonomous Driving Camera) 5 problems exist ⊙ADAS		
1.7E0197	Autonomous Driving Camera: Field Of Vision Impaired For A Short Time	Intermittent
2.E05627	Signal (Infotainment, Automated Driving Report) Invalid, Transmitter HU	Intermittent
3.E056EE	Signal (Running Gear, Provision Of Intrinsic Motion Signal) Invalid, Transmitter VIP	Intermittent
4.BA0ACC	Lane Departure Warning Function Not Available	Intermittent
5.BA0ACA	Lane Change Warning Function Not Available	Intermittent
GWS (Gear Selector Switch) 2 problems exist		

1.E09400	No Message (Transmission Train Data Display, 0x3FD), Receiver GWS, Transmitter EGS / CCU	Intermittent
2.E09403	No Message (Chassis, 0x2B7), Receiver GWS, Transmitter HU / KOMBI	Intermittent
HU-H (Headunit High) 4 problems exist		
1.031791	HU-H: Function Resrtriction Bluetooth Connection	Intermittent
2.031798	HU-H: Functional Limitation For Bluetooth Audio Browsing	Intermittent
3.031793	HU-H: Function Restriction Connection WLAN	Intermittent
4.03179A	HU-H: Function Restriction Connection Apple CarPlay	Intermittent
EME2 (Electrical Machine Electronics 2) 5 problems exist		
1.E4D4B0	No Message (Vehicle Speed, ID: V_VEH) Missing, Receiver EME2, Transmitter DSC	Intermittent
2.E4D409	Message (Request Of Front Axle Speed, 0x128) Not Current, Receiver EME2, Transmitter DSC	Intermittent
3.E4D405	Message (Request Of Rear Axle Speed, 0x128) Not Current, Receiver EME2, Transmitter DSC	Intermittent
4.E4D898	No Message (SecureDateAndTimeSDaT, ID: SecureDateAndTimeSDaT)	Permanent
5.E4D89C	No Message (SecureDateAndTimeSDaTQualifying, ID: SecureDateAndTimeSDaTQualifying)	Permanent
The following systems are OK:		
1.ACSM (Crash Safety Module)		
2.HVS (Battery Management Electronics)		
3.RLMAL (Outer Left Rear Light Module)		
4.RLMAR (Outer Right Rear Light Module)		
5.SRSNVR (Side Radar Sensor Near Range Front Right)	ADAS	
6.SRSNVL (Side Radar Sensor Near Range Front Left)	ADAS	
7.DSC (Dynamic Stability Control (DSC))		
8.EPS (Electromechanical Power Steering)		
9.RAM (Receiver Audio Module)		
10.RSNECU (Short Range Control Unit Radar Sensors)		
11.FLEL (Frontal Light Electronics Left)	ADAS	
12.FLER (Frontal Light Electronics Right)	ADAS	
13.SPNMVL (Front Left Seat Inflator Module)		
14.KOMBI (Instrument Panel)		

15.TCB (Telematic Communication Box)

16.CON (Controller)

17.SMFA (Seat Module, Driver)

18.SMBF (Front Passenger Seat Module)

19.AHM (Trailer Module)

20.TSGFA (Door Control Unit, Driver's Door)

21.TSGBF (Door Control Unit, Passenger Door)

22.TSGFAH (Door Control Unit, Rear Driver's Side)

23.TSGBFH (Door Control Unit, Rear Passenger Side)

ADAS