

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information



Year:2021
 Make:Fiat
 Model:Aegea / Tipo Sedan / HB / SW
 VIN:ZFACF7D38M6T73712
 Vehicle Software Version:V38.80
 Diagnostic Application Version:V8.00.037
 Diagnostic path:FIAT > Aegea / Tipo Sedan / HB / SW > 2021

Repair Shop

Shop Name:Autopoint Ljubljana
 Address: Devova 6 Ljubljana | Slovenia
 Zip Code:1000
 Telephone:+38631302033
 Email:info@autopoint.si
 SN:988774059376
 Test Time:2026-04-29 08:49:42



System fault code 【Pre-Repair】

The following systems is abnormal:

Parking Assistant Module (PAM)

DTC (1)

1.U1933-86 BCM Command (From Body Computer Module) - Signal Invalid Stored

Instrument Panel Cluster (IPC)

DTC (3)

1.B1037-87 BCM (BCM Command) (Signal From Body Computer Module) - Missing Message Stored

2.U1710-87 Electronic Climate Control (ECC) - Missing Message Stored

3.B2206-64 Current VIN Missing / Mismatch - Signal plausibility failure Stored

The following systems are OK:

- 1.Body Control Module (BCM)
- 2.Engine Control Module (ECM)
- 3.Anti-Lock Braking System (ABS)
- 4.Occupant Restraint (ORC)

5. Electronic Power Steering (EPS)

6. Haptical Lane Feedback (HALF)



7. Entertainment Telematic Module (ETM)

8. Heating Ventilation Air-Conditioning And Cooling (HVAC)

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!