

Vehicle Diagnostic Report

The Report is created by **LAUNCH** X-431

Vehicle Information



Year:2023
Make:Peugeot
Model:308 (P5)
VIN:VR3F3DGYTPY512928
Odometer:59192 km
Vehicle Software Version:V44.21
Diagnostic Application Version:V8.00.039

Repair Shop

Shop Name:Autopoint Ljubljana
Address: Devova 6 Ljubljana | Slovenia
Zip Code:1000
Telephone:+38631302033
Email:info@autopoint.si
SN:988774059376
Test Time:2026-08-11 13:33:01



System fault code 【Pre-Repair】

The following systems are OK:

- 1.Built-In Systems Interface(Bsi)
- 2.Engine ECU
- 3.Gearbox
- 4.Anti-Lock Braking System (ABS) Or Electric Stability Program (ESP)
- 5.Air Bags
- 6.Electric Machine Management ECU
- 7.Traction Battery ECU
- 8.On-Board Charger / Direct Voltage Transformer Assembly
- 9.Electric / Hybrid Drive Train Supervisor ECU
- 10.Ancillaries Battery Switch 1
- 11.Ancillaries Battery Switch 2
- 12.Electrical Brake Servo Master Cylinder
- 13.Power Steering
- 14.Battery Charge Status Unit
- 15.Controls On The Steering Wheel

- 16.Multplexed Control Panel
- 17.Seat Belt Not Fastened LED Unit(Tnb)
- 18.Windscreen Wiper
- 19.Rain-Sunlight Sensor
- 20.Parking Assistance
- 21.Touch Screen
- 22.Hands Full Access ECU, Right-Hand Side Or Rear
- 23.Vehicle Distance Assistance
- 24.Multifunction Video Camera (CMF)
- 25.Panoramic Visual Assistance ECU

⦿ ADAS
⦿ ADAS
⦿ ADAS

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!