

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE AUTO  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 15/10/2021  
**Vehicle identification number:** WBA11AR030CJ13205  
**Database:** Manually  
**Odometer reading:** 6 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input type="checkbox"/>	-	Engine oil	
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	-	Brake fluid	
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input checked="" type="checkbox"/>	14 days ago	Pre-delivery inspection	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	-	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Standard scope	

---

Legend:

Linked with

Services whose due dates are linked to another service item

- Service carried out
- Service due but not carried out
- Service not carried out
- 2.000 km Remaining distance up to due date
- 2.000 km Excessive distance
- Remaining runtime and distance unknown

---

GRANVILLE, 15/10/2021

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE AUTO GRANVILLE  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 06/07/2022

**Vehicle identification number:** WBA11AR030CJ13205

**Database:** Manually

**Odometer reading:** 33,072 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input checked="" type="checkbox"/>	-70 km / in about 1 year	Engine oil	Microfilter (consider further additional job(s) if appropriate)
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	in about 2 years	Brake fluid	
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in about 3 years	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input type="checkbox"/>	-	Air filter element	
	<input type="checkbox"/>	33,000 km / in about 3 years	Vehicle check	
	<input checked="" type="checkbox"/>	-70 km / in about 1 year	Microfilter (consider further additional job(s) if appropriate)	
	<input type="checkbox"/>	-	Spark plugs	



-

Standard scope

---

Legend:

Linked with                      Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown

---

GRANVILLE, 06/07/2022

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE GRANVILLE  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 17/04/2023

**Vehicle identification number:** WBA11AR030CJ13205

**Database:** Manually

**Odometer reading:** 66,580 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input checked="" type="checkbox"/>	-500 km / in about 1 year	Engine oil	Air filter element, Microfilter (consider further additional job(s) if appropriate), Spark plugs
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	in over 1 year	Brake fluid	Check gas pressure springs for bonnet
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in over 2 years	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input checked="" type="checkbox"/>	-500 km / in about 1 year	Air filter element	
	<input type="checkbox"/>	in over 1 year	Check gas pressure springs for bonnet	
	<input checked="" type="checkbox"/>	-500 km / in about 1 year	Vehicle check	
	<input checked="" type="checkbox"/>	-500 km / in about 1 year	Microfilter (consider further additional job(s) if appropriate)	



-500 km / in  
about 1  
year Spark plugs



- Standard scope

---

Legend:

Linked with Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown

---

GRANVILLE, 17/04/2023

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE GRANVILLE  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 08/03/2024

**Vehicle identification number:** WBA11AR030CJ13205

**Database:** Manually

**Odometer reading:** 99,578 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input checked="" type="checkbox"/>	10 km / in about 1 year	Engine oil	Microfilter (consider further additional job(s) if appropriate)
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	in 7 months	Brake fluid	Check gas pressure springs for bonnet
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in over 1 year	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input type="checkbox"/>	-	Air filter element	
	<input type="checkbox"/>	in 7 months	Check gas pressure springs for bonnet	
	<input type="checkbox"/>	34,000 km / in about 3 years	Vehicle check	
	<input checked="" type="checkbox"/>	10 km / in about 1 year	Microfilter (consider further additional job(s) if appropriate)	



-

Spark plugs



-

Standard scope

---

Legend:

Linked with                      Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown

---

GRANVILLE, 08/03/2024

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE GRANVILLE  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 22/10/2024

**Vehicle identification number:** WBA11AR030CJ13205

**Database:** Manually

**Odometer reading:** 120,280 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input type="checkbox"/>	13,000 km / in over 1 year	Engine oil	Air filter element, Microfilter (consider further additional job(s) if appropriate), Spark plugs
	<input type="checkbox"/>	-	Front Brake	
	<input checked="" type="checkbox"/>	21 days ago	Brake fluid	Check gas pressure springs for bonnet
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in 11 months	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input type="checkbox"/>	13,000 km / in over 1 year	Air filter element	
	<input checked="" type="checkbox"/>	21 days ago	Check gas pressure springs for bonnet	
	<input type="checkbox"/>	13,000 km / in over 1 year	Vehicle check	
	<input type="checkbox"/>	13,000 km / in over 1 year	Microfilter (consider further additional job(s) if appropriate)	



13,000 km /  
in over 1  
year Spark plugs



- Standard scope

---

Legend:

Linked with Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown

---

GRANVILLE, 22/10/2024

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE GRANVILLE  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 25/02/2025

**Vehicle identification number:** WBA11AR030CJ13205

**Database:** Manually

**Odometer reading:** 132,823 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input checked="" type="checkbox"/>	-240 km / in about 1 year	Engine oil	Air filter element, Microfilter (consider further additional job(s) if appropriate), Spark plugs
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	in over 1 year	Brake fluid	Check gas pressure springs for bonnet
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in 7 months	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input checked="" type="checkbox"/>	-240 km / in about 1 year	Air filter element	
	<input type="checkbox"/>	in over 1 year	Check gas pressure springs for bonnet	
	<input checked="" type="checkbox"/>	-240 km / in about 1 year	Vehicle check	
	<input checked="" type="checkbox"/>	-240 km / in about 1 year	Microfilter (consider further additional job(s) if appropriate)	



-240 km / in  
about 1  
year Spark plugs



- Standard scope

---

Legend:

Linked with Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown

---

GRANVILLE, 25/02/2025

# Proof of maintenance

## Entry in the service history

**Service workshop:** ENVERGURE GRANVILLE  
139, RUE DES ENTREPRENEURS  
50400, GRANVILLE  
FR

**Phone:**

**Email address**

---

**Maintenance date:** 14/01/2026

**Vehicle identification number:** WBA11AR030CJ13205

**Database:** Manually

**Odometer reading:** 161,954 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input checked="" type="checkbox"/>	3,900 km / in about 1 year	Engine oil	Microfilter (consider further additional job(s) if appropriate)
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	in 9 months	Brake fluid	Check gas pressure springs for bonnet
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in over 1 year	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input type="checkbox"/>	-	Air filter element	
	<input type="checkbox"/>	in 9 months	Check gas pressure springs for bonnet	
	<input type="checkbox"/>	37,000 km / in about 3 years	Vehicle check	
	<input checked="" type="checkbox"/>	3,900 km / in about 1 year	Microfilter (consider further additional job(s) if appro- priate)	



-

Spark plugs



-

Standard scope

---

Legend:

Linked with                      Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown

---

GRANVILLE, 14/01/2026

# Proof of maintenance

## Entry in the service history

**Service workshop:** DAMJAN DEČMAN  
GROBELNO - DEL 137  
3231, GROBELNO  
SI

**Phone:**

**Email address**

---

**Maintenance date:** 11/03/2026  
**Vehicle identification number:** WBA11AR030CJ13205  
**Database:** Manually  
**Odometer reading:** 162,344 km

We performed the following work on your vehicle today:

Symbol	Status	Remaining	Description	Linked with
	<input type="checkbox"/>	in almost 2 years	Engine oil	Air filter element, Microfilter (consider further additional job(s) if appropriate), Spark plugs
	<input type="checkbox"/>	-	Front Brake	
	<input type="checkbox"/>	in 7 months	Brake fluid	Check gas pressure springs for bonnet
	<input type="checkbox"/>	-	Rear Brake	
	<input type="checkbox"/>	-	Particle filter	
	<input type="checkbox"/>	-	Vehicle check	
	<input type="checkbox"/>	-	Service pre-check for roadworthiness test (for German market only)	
	<input type="checkbox"/>	in over 1 year	Statutory vehicle inspection	
	<input type="checkbox"/>	-	Statutory emissions test	
	<input type="checkbox"/>	in almost 2 years	Air filter element	
	<input type="checkbox"/>	in 7 months	Check gas pressure springs for bonnet	
	<input type="checkbox"/>	in almost 2 years	Vehicle check	
	<input type="checkbox"/>	in almost 2 years	Microfilter (consider further additional job(s) if appropriate)	
	<input type="checkbox"/>	in almost 2 years	Spark plugs	



-

Standard scope

---

Legend:

Linked with                      Services whose due dates are linked to another service item



Service carried out



Service due but not carried out



Service not carried out

2.000 km

Remaining distance up to due date

-2.000 km

Excessive distance

-

Remaining runtime and distance unknown